

Fiber Optic Cleaning Kits

optimize!
softing

XpertClean

Fiber optic cleaning is always required before connecting and before testing a fiber optic cable. In the past, gathering the right set of cleaning supplies, and understanding their use, required time and research. With Softing XpertClean kits, which includes a CleanMachine push and click cleaner for bulk cleaning, and CleanSlide for specialty connectors such as APC, fiber optic cleaning is bundled and easy. The XpertClean process saves you time cleaning and troubleshooting resulting in clean fiber optic end faces and maximum network performance.



Product Description

The **CleanMachine** is the easy to use cleaning tool for fast and reliable end face cleaning. End faces in bulkheads or on cable assemblies are both effortlessly cleaned the first time, every time. The CleanMachine has an easy to use mechanism that advances fabric over a cleaning tip with just a short push and click of the tool.



- Cleans connectors on backplane and on jumpers
- Part of the XpertClean process for first time cleaning, every time
- Used to meet or exceed IEC 61300-3-35, IEC TR62627-01, and Telcordia GR-2923-CORE and SAE
- Aerospace AIR6031
- Effective for the widest range of contaminants
- Easy to use for quick and reliable cleaning
- Rugged and durable, great for all work sites
- Magnetic backing for easy rack placement
- Over 800 clicks per 2 mm and 1.25 mm machine and over 500 clicks with the MPO machine


Typical Applications

- End face connector cleaning
- Cleaning patchcord connectors
- Cleaning bulk-head connections
- Blue CleanMachine is made for 2.5 mm SC, ST, FC connectors
- Orange CleanMachine is made for 1.25 mm LC connectors

XpertClean Process for CleanMachine

Usage Instructions

Insert the CleanMachine tip into the connector, and push in the tool 2-3 clicks advancing the fabric, perfectly cleaning the end face. The XpertClean process eliminates all debris and contamination the first time, avoiding expensive rework and truck-rolls from bad connections.



Kits for LC, ST, SC, FC, MU, PC, and APC connectors

Part number: XC-AC-CKIT-FIBER



Contact:

NORTH AMERICA

Softing Inc.
7209 Chapman Hwy
Knoxville, TN 37920

E-mail: sales@softing.us

Phone: +1.865.251.5252

Each kit (XC-AC-CKIT-FIBER) includes:

XpertClean for LC, ST, SC, FC, MU, PC, APC Fiber Optic End Faces

- 1 – CleanMachine for 1.25 mm LC connectors, XC-AC-CMACH-LC
- 1 – CleanMachine for 2.5 mm SC, ST, FC connectors, XC-AC-CMACH-STSCFC
- 1 – CleanSlide for SC, FC, ST, MU, PC, and APC, XC-AC-CSLIDE